

Work Order (Bid Form)

W	0	RK	OR	DE	RII	VFO	RMA	TION

Work Order Name:

Work Order Type: Weatherization
Audit Name: HAYWOOD

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0355

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: Murley, Rickey

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone:

Cell Phone:

Email Address:

Company Name & Licens	e Number:	 	
Contractor's Signature:		 	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-772-9436

Client Name:

Client ID:

Work Order (Bid Form)

Work Order Name:

DOE Weatherization Assistant

Version 8.5.0

Measures

	Measure 1 Infilt	tration Redctn			Componen	ts		/	nspected
C	Comment								
					Estimated	NAME OF THE OWNER OWNER OF THE OWNER OWNE		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Closed in carport replace light switch cover, seal door frame seal under wall paper border. Seal outlet by book case	Each	1				Jonaton Jona Jona Jona Jona Jona Jona Jona Jo	
2	Labor	Labor	Hour			PARAMETER SALVANDARIA COMPRESANDARIA			
3	Construction Materials/Hardwar e	Seal around breaker box and crwon molding in closed in carport	Each	1		franchis Asia			
4	Labor	Labor	Hour			MPA NASA YORAN PALASPERANCA SANDA SANDA PARAMANAN PARAMA			
5	Construction Materials/Hardwar e	Laundry room seal plumbing box. Soth side addition seal between D3 door	Each	1					e de la constante de la consta
6	Labor	Labor	Hour					7	Ş
7	Construction Materials/Hardwar e	Kitchen seal pipes under sink. Weather-strip D1,D2 and D3 doors	Each			***************************************			
8	Labor	Labor	Hour						
C	ther Detail								
			To the department of the						
						M day		Live of American	2
			į	Measure	e Sub Total:		5	Sub Total:	
THE STREET AND A TRANSPORTED AND AMERICAN STREET	Field Notes:								

	H Pipe Insulation			Component	ts		I	nspecte
Comment				_				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
I Insulation	DHW Pipe Insulation	Each	1		ane and an			
2 Labor	Labor	Hour	1					
Other Detail				[1 [
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:	H Tank Insulation			Componen	ts.			inspecte
	H Tank Insulation			Component				inspecte
Measure 3 DW		Unito	**************************************	Estimated		Oftic	Actual	
Measure 3 DW Comment Material / Labor	H Tank Insulation Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	-		Qty		Total
Measure 3 DW Comment Material / Labor Hot Water Equipment	Description / Comment		Qty	Estimated		Qty	Actual	
Measure 3 DW Comment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
Measure 3 DW Comment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
Measure 3 DW Comment Material / Labor Hot Water	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated			Actual	

Measure 4 CO	Vionitor is Needed			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1	Terror de la constante de la c				
2 Labor	Labor	Hour	1					
Other Detail		[1 : F		1		
] []		
						1		
			Measur	e Sub Total:		-	Sub Total:	-
	Any Other Heating Syst non-vneted heaters that			Componen xygen deple Estimated	tion sens	or	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Install Counter Flow Direct Vent Heater 50- 55 KBTU Natural Gas heater	Each	1				1000	
2 Labor	Labor	Hour	1					
Other Detail							,	
			-					
			Measur	e Sub Total:			Sub Total:	A VALENTINE STORY
Field Notes:								

Work Order (Bid Form)
Work Order Name:

DOE Weatherization Assistant Version 8.5.0

	Other Problems ement/Crawlspace)			Component	'S			Inspecte
Comment				Estimated			Actual	
		11.14-	O4	Unit Cost	Total	Qty	Unit Cost	Total
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	i Otai	Qly	Om Cost	iotai
1 Health and Safety Items	Repair fallen down insulation and repalce as needed	Each	1	To the second				
2 Labor	Labor	Hour	1		44/1			
Other Detail						, ,		
			Weasur	e Sub Total:] ,	Sub Total:	
						4.444		
	Other Water Heating Pro	oblem		Componen	ts		Actual	Inspecte
Comment	-	oblem <i>Unit</i> s	Qty	-	ts Total	Qty		Inspecte
Comment # Material / Labor	Description / Comment Repalce water heater with electric 4o gallon plumb pop-off		and the second s	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment Repalce water heater with electric 4o gallon	Units	Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment Repalce water heater with electric 4o gallon plumb pop-off	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Repalce water heater with electric 4o gallon plumb pop-off	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Repalce water heater with electric 4o gallon plumb pop-off	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Repalce water heater with electric 4o gallon plumb pop-off	Units Each Hour	Qty 1	Estimated			Actual	

DOE Weatherization Assistant Version 8.5.0

	Measure 8 Pres	sureRelief Piping Need	led		Componen	ts			Inspected
C	Comment				F-dimental			Actual	
					Estimated		04.	Unit Cost	Total
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Omi Cost	TOLAI
1	Health and Safety Items	Pressure relief piping	Each	1					
2	Labor	Labor	Hour	1		man a superior de la company de la compa			
C	Other Detail						, ,		
									1000
				41.4					NAME OF THE PARTY
				Measur	e Sub Total:			Sub Total:	
-									
	Measure 9 Smo	ke Detector is Needed			Componen	ts			Inspected
	Measure 9 Smo	ke Detector is Needed			Componen Estimated			Actual	Inspected
C		ke Detector is Needed Description / Comment	Units	Qty	-		Qty		Inspected Total
<i>C</i>	comment		<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
# 1	Comment Material / Labor Health and Safety	Description / Comment			Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Items	Description / Comment Smoke detector	Each	1	Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Items Labor	Description / Comment Smoke detector	Each	1	Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Items Labor	Description / Comment Smoke detector	Each	1	Estimated		Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Items Labor	Description / Comment Smoke detector	Each Hour	1	Estimated			Actual	

Work Order (Bid Form)
Work Order Nama:

DOE Weatherization Assistant Version 8.5.0

Measure 10 Vapor Barrier Needed (Basement/Crawlspace)			Components					Inspected		
C	omment				Entimated			Actual		
					Estimated					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Basement / crawlspace vapor barrier	Each	1						
2	Labor	Labor	Hour	1						
	Other Detail									
					A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the state of t				
ſ										
<u></u>	and the second s		Вашина македан са поточно на пото	Measur	e Sub Total:			Sub Total:		
The second secon	Field Notes:									
			Work Oi	der Gra	nd Total:		Gran	d Total:		

Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Work Order Nama: